

0010



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 9/14/2000 / 10:00 a.m. - 3:30p.m.
Date of Last Inspection: 8/9/2000

SW
by
JO

Mine Name: Hidden Valley Mine County: Emery Permit Number: ACT/015/007
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 566, Sesser, Illinois 62884
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Not Present during the inspection; conversed with him on 9/19/2000
State Official(s): Bill Malencik Federal Official(s): None
Weather Conditions: Clear
Existing Acreage: Permitted 950 Disturbed 7 Regraded Seeded
Status: Exploration Active XXX Inactive Temporary Cessation Bond Forfeiture
Reclamation (Phase I Phase II Final Bond Release Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 9/14/2000

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

-The general area, including the mine, received a second storm in the form of rain on Sunday. The only sign of runoff was in the undisturbed drainage and Ivie Creek.

-No violations were issued. The environmental control measures appear to meet the coal rule performance standards.

-Mr. Behling stated he would be taking flow water samples the latter part of September.

-Was advised by Mr. Behling that because of drought conditions they would not reclaim the A seam and the reclaimed road.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and showed no evidence of recent runoff. The diversion above the "A" seam maintained this past summer, meets performance standards. Some fine material from the escarpment is being deposited in the diversion, but doesn't constitute a concern at this point in time.

8. NONCOAL WASTE

The noncoal waste on the surface is not a problem. The exception is at the end of the county road. However, no significant noncoal waste, pop cans, etc. were observed during the instant inspection.

13. REVEGETATION

The perennial grass plant are dormant, likewise the annuals with the exception of a small Halogeton that germinated as a result of the last storm. The brouse plants are doing the best, in spite of the dry conditions.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Emery County repaired the county road into and out of the permitted area. The work consisted of repairing the drainage across the road. Also, some bumps were repaired.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 9/14/2000

21. BONDING AND INSURANCE

Insurance expires 11/5/2000. The surety bond is on records for \$90,758.00 and no bond release has been approved by the Division.

Inspector's Signature: _____


Wm. J. Malencik #26

Date: September 22, 2000

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
Tim Kirschbaum, Consol, Illinois
Steve Behling, Consol, Emery
Price Field office

O:\015007.HID\Compliance\2000\p_0914.wpd